

URS 5885

100% SOLIDS BRUSHABLE URETHANE SYSTEM

DESCRIPTION

URS 5885 is a room temperature curing, two component urethane designed for easy mixing and application. Apply 150 mils thickness in one application without sagging or slumping. Cures to a medium hard coating, 85 Shore A, in varied environments. Excellent for lining a protecting hoppers, chutes, fans, pumps, vibrating and pneumatic conveying equipment.

LIQUID PROPERTIES

ISO 540A

AMN 1070B

MIXED

Appearance	Clear / Lt. Amber	Black	Grey
Weight per Gallon	9.80-10.00	8.30-8.70	9.50-9.70
Viscosity 7 Deg F	5000-7000cps	100-300cps	(semi-putty)

PHYSICAL PROPERTIES

Hardness, Shore A	84-86
Tensile Strength, psi	3500
Elongation, %	600
Tear Strength, Die C	400
Tear Strength, Split Tear	74
Resilience, %	40
Abrasion Resistance, (Tabor Index) H-18 Wheel 1,000 Cycles	95 mg Loss

SURFACE PREPARATION

Completely clean and dry all surfaces to be coated. Fiberglass, rubber, wood, galvanized, aluminum, stainless steel, brick and concrete are acceptable surfaces. All substrate should be prepared with proper adhesives. Metal surfaces should be sandblasted per SSPC – SP 5-63 “White Metal Blasting Cleaning”

- Concrete surfaces should be acid etched for immersion applications.
- A 4 mil surface profile is desirable.

If an adhesive is required use FORSCH ADHESIVE 1001.

URS 5885 cont

PROCESSING PARAMETERS

Apply with a brush, initial build for one coat is 50 mils. 150 mils maximum build for uncured coating.

MIXING INSTRUCTIONS

- A. Stir Part B thoroughly and pour into Part A container
- B. Mix 1 ½ to 2 minutes in container using wood mixing stick (a rapid figure 8 stirring motion is best to ensure good mixing with least air entrapment.)
- C. Transfer mixed compounds to clean plastic or metal container and mix for 1 minute more.
- D. If mixing less than full contents, use mix ratio of 100.00 Part A to 20.00 Part B by weight. Accurate mixing is critical for the best performance of this product.

POT LIFE: 10 minutes at 75 Deg F for fast version
45 minutes at 75 Deg F for slow version

CURE TIME: 80% Cure 24 hours @ 75 Deg F.
100% Cure 48 hours @ 75 Deg F.

LIMITATION: Part A must be clear and fluid when used. Exposure to cool temperatures below zero Deg F. or to extend storage below 30 Deg F. may cause Part A to crystallize. This will not harm Part A, however, it must be warmed at 90 to 150 Deg F. until Completely melted. Cool to room temperature before using.

STORAGE

Systems should be stored unopened in air tight containers at 60 – 90 degrees F. Partially emptied containers should be swept free of atmospheric moisture with dry nitrogen before sealing.

HANDLING PRECAUTIONS

For complete and updated health and safety information, read the MATERIAL SAFETY DATA SHEETS. Do not handle or use until the MATERIAL SAFETY DATA SHEET has been read and understood.